ABANDONMENT OF UNDERGROUND STORAGE TANK PERMIT REQUIREMENTS

- 1. Prepare a map showing the address, assessor's parcel number, tank size, and tank location in relation to the structures on the property.
- 2. Secure work area with safety lines or barricades before beginning
- 3. Locate and mark underground utilities.
- 4. Remove all potential sources of ignition.
- 5. Ground motorized equipment.
- 6. Remove all flammable or combustible liquids from the tank and connected piping.
- 7. Disconnect the suction, inlet, gauge, vapor return, and vapor lines.
- 8. Fill the tank completely, in the presence of an inspector, with an inert solid material approved by RFD.
- 9. Cap or plug remaining underground piping.

Additional requirements are subject to review and inspection of the operation.